MATERIAL SAFETY DATA SHEET



FREMONT INDUSTRIES, INC.

4400 Valley Industrial Blvd. N.

P.O. Box 67

Shakopee, MN 55379-1859

PHONE: (952) 445-4121

FAX: (952) 496-3027

EMERGENCY PHONE: (952) 445-4121

CHEMTREC: (800) 424-9300

FREMONT 8576

SECTION I GENERAL INFORMATION

NAME ON LABEL (Identity): FREMONT 8576 Steam Line Treatment

CHEMICAL FAMILY: Base

HMIS HAZARD CODES: Health (2) Flammability (2) Reactivity (0)

NFPA HAZARD CODES: Health (2) Flammability (2) Reactivity (0) Special Hazard: NA HAZARD RATING SCALE: 4 = Severe 3 = Serious 2 = Moderate 1 = Slight 0 = Minimal

SECTION II HAZARDOUS INGREDIENTS

PRINCIPAL HAZARDOUS COMPOUNDS	PERCENT	OSHA	ACGIH		
(CHEMICAL & COMMON NAME(S)	(OPTIONAL)	PEL	TLV	CAS#	
2-Diethylaminoethanol	20	10 ppm	2 ppm	100-37-8	
		(50 mg/M^3)			
Morpholine	10	20 ppm	20 ppm (Skin)	110-91-8	

NA = Not Applicable NE = Not Established

SECTION III PHYSICAL DATA

BOILING POINT (°F): 212° F (or greater than) SPECIFIC GRAVITY ($H_2O = 1$): 0.99

VAPOR PRESSURE (mm Hg): NE SOLUBILITY IN WATER: Complete VAPOR DENSITY (Air = 1): NE

EVAPORATION RATE (BuAc = 1): NE

MELTING POINT (°F): NE

APPEARANCE AND ODOR: Clear to light amber colored liquid with an ammoniacal odor.

SECTION IV FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method Used): NE (T.C.C.)

FLAMMABLE LIMITS: LEL: NE UEL: NE

EXTINGUISHING MEDIA: Water spray, carbon dioxide, alcohol foam, dry chemical.

AUTO-IGNITION TEMPERATURE: NE

SPECIAL FIRE FIGHTING PROCEDURES: Firefighters should wear all protective equipment including self-contained breathing apparatus when exposed to smoke, fumes or hazardous decomposition products.

UNUSUAL FIRE AND EXPLOSION HAZARDS: Keep metal containers cool with water spray.

SECTION V REACTIVITY DATA

STABILITY: Unstable ____ Stable __X

CONDITIONS TO AVOID: Strong acids, extreme heat. INCOMPATIBILITY (Materials to Avoid): Oxidizing agents.

HAZARDOUS POLYMERIZATION: Will Not Occur X May Occur

CONDITIONS TO AVOID: None known.

HAZARDOUS DECOMPOSITION PRODUCTS: Oxides of carbon and nitrogen.

SECTION VI HEALTH HAZARD DATA

ROUTE(S) OF ENTRY: Contact with skin, eyes, and mucous membranes. Inhalation. Absorption through skin.

HEALTH HAZARDS: Acute - Irritation or burns to skin, mucous membranes, respiratory tract, and especially eyes.

Chronic - Severe burns or ulceration of body tissues.

MATERIAL SAFETY DATA SHEET



FREMONT INDUSTRIES, INC.

4400 Valley Industrial Blvd. N.

P.O. Box 67

Shakopee, MN 55379-1859

PHONE: (952) 445-4121

FAX: (952) 496-3027

EMERGENCY PHONE: (952) 445-4121

CHEMTREC: (800) 424-9300

FREMONT 8576

SECTION VI	HEALTH HAZARD	DATA	(continued)
------------	----------------------	------	-------------

CHEMICAL LISTED AS CARCINOGEN OR POTENTIAL CARCINOGEN: Yes___ No _X_

NATIONAL TOXICOLOGY PROGRAM: Yes ____ No _X

I.A.R.C. MONOGRAPHS: Yes No X OSHA: Yes No X

SIGNS AND SYMPTOMS OF EXPOSURE: Reddening, burning or itching of skin; watering or blurring of eyes; breathing difficulties.

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE: Respiratory or skin irritation; possible burns to eyes; breathing difficulties.

EMERGENCY AND FIRST AID PROCEDURES:

EYES: Flush immediately with cool water for 15 minutes. Contact physician immediately.

SKIN: Remove contaminated clothing. Flush affected area with cool water for 15 minutes. Contact physician for persistent irritation.

INHALATION: Remove to fresh air. Contact physician for persistent irritation.

INGESTION: DO NOT INDUCE VOMITING. Give large volumes of water. Contact physician and/or Chemtrec immediately.

SECTION VII PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Wear all protective equipment. Contain spill and absorb on inert material (i.e. vermiculite). Containerize. Flush remainder to drain with excess water, maintaining discharge pH limits. Use adequate ventilation.

WASTE DISPOSAL METHOD: Dispose of in accordance with federal, state and local regulations.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Wear all protective equipment. Use with adequate ventilation. Store away from high heat or ignition sources. Store away from oxidizers.

OTHER PRECAUTIONS: Keep container closed when not in use. Wash thoroughly after handling. Mist is irritating. Store at room temperature.

SECTION VIII SPECIAL PROTECTION INFORMATION AND CONTROL MEASURES

RESPIRATORY PROTECTION (Specify Type): NIOSH/MSHA approved for amine and ammonia vapors (TC-23C-440; e.g. 3M Series 7000 respirator with 7254 cartridges).

VENTILATION: LOCAL EXHAUST: Recommended

MECHANICAL (General): X SPECIAL: NA OTHER: NA

PROTECTIVE GLOVES: Rubber

EYE PROTECTION: Splash proof safety goggles or full face shield.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT: Full cover clothing, including long sleeves. Eye wash in immediate vicinity.

WORK/HYGIENIC PRACTICES: Wear all protective equipment. Wash thoroughly after handling. Do not smoke near containers. Store away from food. Wash contaminated clothing before re-use.

MATERIAL SAFETY DATA SHEET



FREMONT INDUSTRIES, INC.

PHONE: (952) 445-4121 4400 Valley Industrial Blvd. N. FAX: (952) 496-3027 P.O. Box 67 **EMERGENCY PHONE**: (952) 445-4121

Shakopee, MN 55379-1859 **CHEMTREC:** (800) 424-9300

1/4/00

FREMONT 8576

SECTION IX REGULATORY INFORMATION

CERCLA 40 CFR 302.4: NA

SARA TITLE III:

Section 302/304: NA

Section 311/312 Hazard Category: Acute

Section 313: NA

Bruce Busch (Chemist) 5/31/05

Prepared by (Optional) Issue Date Supersedes

We believe the information contained herein, including data, recommendations and other items set forth are reliable, but they are given without warranty of any kind, expressed or implied, as to the accuracy, completeness, dependability, or reliability thereof, except that such information is, to the best of Fremont's knowledge and belief, accurate as of the date indicated.